


Site and Soil Evaluation for Sewage Treatment and Dispersal

County: Wayne
 Township / Sec.: Baughman
 Property Address/Location: Black Diamond Rd
North Lawrence, OH 44666
 Applicant Name: Kristen Kiko, Kiko Auctions
 Address: 2722 Fulton Rd NW
Canton, OH 44718-3507
 Phone #: 330-234-7110
 Lot #: PPN 02-00271.000
 Test Hole #: 1
 Latitude/Longitude: N 40.876073 W 81.685761
 Method: Pit Auger Probe

Land Use / Vegetation: woods
 Landform: Upland
 Position on Landform: Hillslope
 Percent Slope: 5
 Shape of Slope: Linear
 Weather: rain
 Date Evaluated: 3/19/2025
 Evaluator: Barry D. Cavanna CPSS
4686 Valley Road
Wooster, OH 44691



Certified Professional
 Soil Scientist
BARRY CAVANNA
 19577
 CERTIFICATION #19577



4686 Valley Road
 Wooster, OH 44691
 (925) 628-8187

Signature: _____
 Phone#: 925-628-8187

Soil Profile		Estimating Soil Saturation			Estimating Soil Permeability							Other Soil Features
		Munsell Color (hue, value, chroma)			Texture			Structure				
Horizon	Depth (inches)	Matrix Color	Redoximorphic Features		Class	Approx. % Clay	Approx. % Fragments	Grade	Size	Type (shape)	Consistence	
			Concentrations	Depletions								
Ao	0-4	10YR 4/3			SiL	15		2	m	gr	fr	
BE	4-6	10YR 4/3			SiL	15		2	m	gr	fr	
Bt1	6-18	7.5YR 5/6			SiL	15		2	m	sbk	fi	
Bt2	18-30+	10YR 5/6		10YR 6/2	SiCL	30	10	2	m	sbk	fi	

Limiting Conditions	Depth to (in.)	Descriptive Notes	Remarks / Risk Factors:
Perched Seasonal Water Table	18		
Apparent Water Table	n/a >60		
Highly Permeable Material	n/a >60		
Bedrock	n/a >60		
Restrictive Layer	n/a >60		

Note : The evaluation shall include a complete site plan or site drawing.

ODH - Dec. 2006 - Revised Sept. 2007


Site and Soil Evaluation for Sewage Treatment and Dispersal

County: Wayne
 Township / Sec.: Baughman
 Property Address/Location: Black Diamond Rd
North Lawrence, OH 44666
 Applicant Name: Kristen Kiko, Kiko Auctions
 Address: 2722 Fulton Rd NW
Canton, OH 44718-3507
 Phone #: 330-234-7110
 Lot #: PPN 02-00271.000
 Test Hole #: 2
 Latitude/Longitude: N 40.876083 W 81.68252
 Method: Pit Auger Probe

Land Use / Vegetation: cropland
 Landform: Upland
 Position on Landform: Hillslope
 Percent Slope: 5
 Shape of Slope: Linear
 Weather: rain
 Date Evaluated: 3/19/2025
 Evaluator: Barry D. Cavanna CPSS
4686 Valley Road
Wooster, OH 44691



Certified Professional
 Soil Scientist
BARRY CAVANNA
 CERTIFICATION #19577



4686 Valley Road
 Wooster, OH 44691
 (925) 628-8187

Signature: _____
 Phone#: 925-628-8187

Soil Profile		Estimating Soil Saturation			Estimating Soil Permeability							Other Soil Features
		Munsell Color (hue, value, chroma)			Texture			Structure				
Horizon	Depth (inches)	Matrix Color	Redoximorphic Features		Class	Approx. % Clay	Approx. % Fragments	Grade	Size	Type (shape)	Consistence	
			Concentrations	Depletions								
Ap	0-4	10YR 4/3			SiL	15		2	m	gr	fr	
BE	4-8	10YR 4/3			SiL	15		2	m	gr	fr	
Bt1	8-20	7.5YR 5/6			SiL	15		2	m	sbk	fi	
Bt2	20-36+	10YR 5/6		10YR 6/2	SiCL	30	10	2	m	sbk	fi	

Limiting Conditions	Depth to (in.)	Descriptive Notes	Remarks / Risk Factors:
Perched Seasonal Water Table	20		
Apparent Water Table	n/a >60		
Highly Permeable Material	n/a >60		
Bedrock	n/a >60		
Restrictive Layer	n/a >60		

Note : The evaluation shall include a complete site plan or site drawing.

ODH - Dec. 2006 - Revised Sept. 2007

Black Diamond Rd

Property Lines and Soil Boundaries are Approximate

Legend
TB

TB 1

TB 2

TB 3



